PROJECT STATUS REPORT **INSTRUCTIONS** Entries will be taken from codes listed on the new water which will be taken from codes listed on the new water with the code state of the new water w ITEM 8 Enter concise project progress information sufficiently complete so that reference to other reports will not be nec-ITEM 20 essary. Changes in program scheduling should be fully explained. If additional space is required a separate 8 x 101/2 sheet will be used. Identify particular report and mark proper security classifications. I. PROGRAM STRUCTURE 2. PROJECT NR OR SYSTEM TEST OBJ NR 3. TASK, ESP OR TEST NUMBER 921A 62B01 4. AFFTC PROJECT DIRECTIVE NR 5. ARDC PRIORITY 6. REPORTING PERIOD 62-17 20F May 1963 7. TITLE AND OBJECTIVE EXPERIMENTAL PERSONNEL PARACHUTE (MULTI-STAGE) To determine the opening reliability of a multi-stage parachute assembly to be used by parachutist from high altitudes.

SCHEDULE	CURRENT FY									FY64								E	FY 650TRS FY 66 OTRS													
	J	A	S	0	N	D	J	F	M	A	M	1	1	A	-	0	L.	D	1 .		1			г.						_		
CURRENT SCHEDULE								<u> </u>				_			-	Ü		-	J	F	M	<u> </u>	М	J	lst	24	3d	4th	lat	2d	3d	411
NEW SCHEDULE																																-
сне соре Ј												2	ł																			
9. FIRST FLIGHT/	TES	Τ	10.	LAT	r es	T FL	IG F	1 <b>T</b> /1	rest		11.	FIN	AL	FLIC	I	/TE	ST	12,	TO	ΓAL	FLI	IG H1	ГНЕ	RS R	ΕQ	13.	ACI	T S	ERI	AL I	NR	
14. % PLANNING COMPLETED		15.	% II TIO	N C	RUM	LET	A-	16.	% т СОМ	EST IPL	ING	D D	_	17,	% D .	AT A	RE	טים	710	N	18.	% RI	EPO	RT	CON	4-	19.	% т Рье	OTA	L C	ом•	<del>,</del>
10/90		<del></del>	5	/90	)				70	/9	0					LO/	90						5/0	)					0/8			

LIC 9121 WSC 3

Tests completed: 225

Tests documented: 227

Aircraft hours flown to date:

Documented aircraft hours remaining:

Photo

Test			Photo							
C-130	-	56.1	T-28	٠_	23.4					
B-66	-	36.0	T-33	_	61.0					
			B-57		6.0					
			F-104	_	1.5					
			F-100	-	18.0					
			H-21	-	19.0					
			T-38	-	4.0					

Test C-130 - 13.0

No tests.

On file USAF release instructions apply.

21. DATE 22. OFFICE SYMBOL AND TELEPHONE EXT

23. SIGNATURE OF PROJECT OFFICER
Charles Or James

31 May 1963

FTLGM/266

CWO Charles O. Laine

## Approved For Release 2002/11/1089101A-RDP75B00285R000400020034 PROJECT STATUS REPORT INSTRUCTIONS Entries will be taken from codes listed on MINIMUM NEW MINIMUM Page 3. Enter concise project progress information sufficiently complete so that reference to other reports will not be necessary. Changes in program scheduling should be fully explained. If additional space is required, a separate 8 x 10½ sheet will be used. Identify particular report and mark proper security classifications. RUCTURE | 2. PROJECT NR OR SYSTEM TEST OBJ NR | 3. TASK, ESP OR TEST NUMBER | 2. PROJECT NR OR SYSTEM TEST OBJ NR | 3. TASK, ESP OR TEST NUMBER | 3. TASK, ESP ITEM 20 1. PROGRAM STRUCTURE 60B23 921A 6. REPORTING PERIOD S. ARDC PRIORITY 4. AFFTC PROJECT DIRECTIVE NR May 1963 75A 60 - 2157. TITLE AND OBJECTIVE SUPPORT MISCELLANEOUS AIR FORCE TASKS To support minor, non-reimbursable Air Force tasks on a continuing basis. FY CURRENT FY SCHEDULE D j F MA 0 N M LON F A M CURRENT G C N I N U I N SCHEDULE NEW SCHEDULE CHG CODE O. FIRST FLIGHT/TEST

17. %DATA REDUCTION

18. % REPORT COM-PLETED 19. % TOTAL COM-PLETED

Continuing

20, REMARKS

14. 7 PLANNING COMPLETED

<u>LIC</u> 9110 <u>WSC</u> 3

18. % INSTRUMENTA- 18. % TESTING TION COMPLETED COMPLETED

No tests.

21. DATE

22. OFFICE SYMBOL AND TELEPHONE EXT

31 May 1963

FTLG/260

A. V. Stamm

PREVIOUS EDITIONS OF THIS FORM ARE OBSOLETE.

AFFTC

APR 60

## Approved For Release 2002/11/08: CIA-RDP75B00285R000400020034-9

Program Structure 921A, SUPPORT USAF IG TRAINING FILM, (Cont'd)

actuating mechanism was also provided. The second release was attached to the back of the ejection seat and actuated the seat recovery parachute ripcord. This release was actuated by the seat-man separator mechanism and was set for a 5-second delay. One drop was made at 110 KIAS at 14,000-ft. pressure altitude with the ejection seat and dummy in a head down position. This method of launch resulted in instability of the seat and was not used again. On all drops the dummy was equipped with a standard 50C7024-18 parachute equipped with an F-1B automatic ripcord release set for 6000-ft. pressure altitude. The seat-dummy separation mechanism and automatic releases operated successfully. The dummy was recovered without damage. The rings attached to the bottom of the seat for recovery parachute riser attachment btoke on parachute opening and the seat free fell to impact and received minor damage. The seat was repaired and reused for dummy drops. The rings were replaced with U-bolts.

One drop was made at 110 KIAS at 10,000-ft. pressure altitude with the seat occupied by the articulated dummy followed by three jumpers. The live jumps were made to allow close observation of the seat-dummy action at launch and to acquaint the jumpers with the turbulent air currents caused by in-flight conditions. One drop was made at 110 KIAS at 10,000-ft. pressure altitude. The seat was occupied by an articulated dummy and two jumpers attempted to , jump simultaneously with seat launch and follow the seat-dummy close enough: to take motion pictures. This could not be accomplished due to the acceleration of seat-dummy following launch. One drop was made at 90 KIAS at 10,000ft. pressure altitude with a man in the ejection seat. (On all drops the man was equipped with a standard 50C7024-18 parachute equipped with a F-1B automatic ripcord release set for 5000-ft. pressure altitude and 10 seconds and with a standard HGUP-2 helmet with an MBU-5 oxygen mask.) Four cameramen were located on the ramp of the aircraft to photograph the events. The man operated the manual seat-man separator mechanism approximately four seconds after launch. Good photo coverage was obtained. Four drops were made at 71, 73, 74 and 74 KIAS at 10,000-ft. pressure altitude with a man in the ejection seat and two jumpers jumping one second prior to seat launch to photograph the events. man operated the manual seat-man separator mechanism approximately 5 to 6 seconds after launch. Good photo coverage was obtained of the free fall and seat-man separation. This concludes testing on this program. A report will be prepared.